



P4 WIRING

| # | COL | PN |
|----|-----|----|
| 13 | VO | 7 |
| 15 | GRN | 8 |
| 17 | GRN | 5 |
| 20 | RED | 6 |
| 25 | RED | 3 |
| 29 | YEL | 4 |
| 33 | BRN | 9 |
| 44 | BLK | 12 |
| 45 | GRY | 11 |

- NOTES:
1. SET WIRE #4 (VOLTAGE SELECTION) TO 208, 220, 240 TAP TO MATCH LINE VOLTAGE
 2. VAC PUMPS MUST BE DERATED IF RUN ON OTHER THAN RATED VOLTAGE.

FUSES MUST BE "MDA" TYPE (SLO-BLO)

NOTE:
DO NOT MEASURE HIGH VOLTAGE (APPROX. 20KV) AT PULSING TRANSFORMER

| | | | |
|--|-------|-------------|---------------|
| ITEM | REQ'D | PART NUMBER | NONNENCLATURE |
| TITLE: WIRING DIAGRAM, ADV355, 208-240V | | | |
| MATERIAL: | | | |
| FINISH: | | | |
| UNLESS OTHERWISE SPECIFIED TOLERANCES ARE: FRACT. ± 1/64 ANGLAR 1/2° DECIMAL ± .005 HOLE DIAS ± .005 | | | |
| DO NOT SCALE THIS PRINT | | | |
| ALL DIMENSIONS ARE IN INCHES REMOVE ALL BURRS BREAK ALL SHARP EDGES | | | |
| SIZE | DRWN | RJL | REV |
| B | CHK'D | | |
| | APP'D | | |
| DRAWING NUMBER | | | WD093 |
| DATE | | | 11/30/92 |

